FINAL REPORT FOR THE BERYLLIUM WIPE SAMPLE FROM THE PLUTONIUM FINISHING PLANT, **BUILDING 234-5Z, ROOM 136 –** SAMPLE DELIVERY GROUP 222S20100331

Document No.: 20100331

Ruth A. Bushaw

Advanced Technologies and Laboratories International, Inc.

Date Published


June 3, 2010

ACCREDITED LABORATION 2007192000 ***********

(48 # 184777

AIHA LAP, LLC

Prepared for:



Prepared by:



Robert L. Cathel CH2M Hill Plateau Remediation Co. P.O. Box 850 Richland, WA 99352 509-942-6493

ATL, Inc. P.O. Box 250 Richland, WA 99352-0250 509-373-4314

AUG 1 0 2010

EDMC

R. A. Bushaw, Project Manager

NARRATIVE

FINAL REPORT FOR THE BERYLLIUM WIPE SAMPLE FROM THE PLUTONIUM FINISHING PLANT, BUILDING 234-5Z, ROOM 136 – SAMPLE DELIVERY GROUP 222S20100331

This is the final analytical report for the beryllium wipe sample received at the 222-S Laboratory on March 25, 2010 in good condition and with adequate paperwork and assigned to sample group 20100331. Following the issuance of the preliminary report, the sample was reanalyzed. Results are discussed in the Analytical Summary below.

DISCLAIMERS

- The information contained in this report is intended only for the use of the addressee and should be considered confidential.
- This report shall not be reproduced, except in full, without written approval of the laboratory.
- The results shown in this report pertain only to the actual samples tested.
- These results conform to the referenced requirements and specifications with any deviations or modifications discussed in the following narrative.

PROCEDURES

Method	Preparation Method	Analysis Procedure
SW-846 Method 6010C		LA-505-171, Rev. G-0
SRNL, WRCS-TR-2004-00395	LA-505-114, Rev. B-0	

METHOD MODIFICATION:

LA-505-114: This digestion procedure is a modification of the Westinghouse Savannah River Company (SRNL) Analytical Development Section Method (WRCS-TR-2004-00395, Revision 1, Method #1) Industrial Hygiene Procedure. The SRNL procedure utilizes a drying oven to heat and evaporate the sample and a hot plate for digestion. Laboratory procedure LA-505-114 uses a microwave for digestion. This method is applicable for acid digestion of air filter media, wipes, and bulk materials for Be analysis by inductively coupled plasma. Nitric acid, hydrochloric acid, hydrofluoric acid, and hydrogen peroxide are added to the sample and allowed to stand for one hour prior to microwave digestion.

ANALYTICAL SUMMARY

The sample was analyzed in accordance with ATL-MP-1029, ATL Industrial Hygiene Quality Assurance Project Plan for 222-S Laboratory and Memorandum PFP-LOI-10-0001, Letter of instruction for Analysis or Beryllium Swipe Samples from Glove boxes in the PFP Complex (LOI). The analyses presented in this report meet all requirements of the LOI and ATL-MP-1029. Based on possible matrix interference, the sample was originally diluted by a factor of ten and the IH required detection limit of 0.05 µg/sample was not achieved. Following issuance of the preliminary report, the sample was reanalyzed with no dilution. On the reanalysis, a profile scan was run and a beryllium peak was observed. However, three analytes (aluminum, iron, and copper) saturated the detector and the profile shows interference on the beryllium peak. It is the laboratory's opinion that copper is the interfering element. A post-

20100331

digestion spike gave a low recovery (~ 70%) that fails to meet the typical control limits of 75% - 125% recovery. This failure is an additional indication of matrix interference. An "N" flag was applied to the sample result to indicate the spike failure. A "J" flag was applied to indicate that the result is an estimate due to the matrix interference.

Attachment 1

DATA SUMMARY REPORT

DATA SUMMARY FOR SAMPLE DELIVERY GROUP 222S20100331

Customer	Sample Dortion	I ah Samula ID	Anothria	Standard	Blank	Result	Spike Repor		Onolifiar
Sample ID	painpie i orugii	ലയ ാബസ്ലാ	Antanyte	(% Recovery)	(нg/sample) (н	(µg/sample)	(% Recovery)	(ug/sample)	Quantito
B24W12	Ghost wipe	S10M000265	Beryllium	96.5	<0.0500	0.153	8.69	0.0500	Z.

NA = Not Analyzed, ND = Not Detected J - Estimated N - Spike Outside Range

Attachment 2

ANALYSIS DATE REPORT

20100331

ANALYSIS DATE REPORT

Sample	Customer Sample Id	Method	Prep Method	Preparation Date	Analysis Date
S10M000265	B24W12	ICP-BE	MICROWAVE	04/26/2010 18:30	05/26/2010 10:00

Attachment 3

RECEIPT PAPERWORK

			2	0100331	
ATL	ì			IAIN OF CUSTODY IECKLIST	LO-090-101 Rev <u>PF-0</u>
Date Samples Red Number of Sample Semple Custodian)		Group #: _	20100331
NOT 1442		Sample	Cust	odian to Complete:	
- Control of the Cont	Action	OK? (Y/N)	N/A		Comments
RSACO provided?	?	/			
RSR provided?		/			
Verify GKI is comple	te				
Check that outer cus	stody seal is intact, if present	W.			
Record cooler tempe appropriate	erature in centigrade, as			Check if no cooler and/or	no ice
S siples are intact a	and in good condition	/		If No, provide comments on ba	ack Paint Car
Venify that COC or R containing the follow	RSA is accurate and complete, ing information:				
Client name	and client sample number				
Date and tim	e of sampling			3	
Sampling loc	ation or origin				
Container type	pe, size, and number	V			
Analysis requ	uest is clear	V			
Simulature of regiong sar	persons relinquishing and mples	V			
Da and/or t	time o sample custody	/			
heafy that sample notes COC and/or RS/	umbers on containers match	/	,		
:	perly (e.g., refrigeration)				
Notify the PM imm	nediately if any problems are	e noted	. (A "N	lo" answer requires Project N	Manager resolution.)
			PM to	Complete:	
Samples acceptab	ple for release? Yes	PM	Initials	<u> </u>	1/2010

If No, comment on communication and resolution:

Other Comments: Unable to verify numbers on the container.

Chain of Custody/Sample Analysis Request

	WATER TO THE PARTY OF THE PARTY		•			
	Hanford Company	C.O.C. Number	NA	- - -	7 942-6493 B376145-61	Page of
	Collector Garin Erickson		Contact/Requestor Le	1506 Cathelle	Telephone MSIN	J FAX
	SAF Number F10 - 146		Sample Origin BUs, 134-52, Room 136	00m 136	Purchase Order/Change Code	979 apo
	Project Title PFP Beryllium Swipes - Other Solio	- Solial	Logbook No NA		Ice Chest No NA Te	Temp. $ u_A$
	Shipped To (Lab) #1L 727-5		Method of Shipment Goult Vehicle	out Vehicle	Bill of Lading/Air Bill No.	νĄ
	Protocol		Data Turnaround 45 days	days	Offsite Property No.	ΛA
	Sample No. Lab ID * Date	Time	No./Type Container	Sample Analysis		Preservative
	1455-05779-001 824 12)12	00 11		Bayllium wipe sample from	ال وعال	136 None
	Siomoosies				107-	10-0001
222	Group #					
		·				
	Possible Sample Hazards/Remarks (List all know Pu / d / Be Contermination	S (List all ki	nown wastes) MSDS ∐Yes X No	SPECIAL INSTRUCTIONS	JIONS	Hold Time
	Relinquished By Print Sign	Date/Time	Received By	Print Sign	Date/Time 13/4 Matrix VI	ら)
	Relinquished By Print Sign KREG DASSEL KENNY	Date/Time /	305 Received By	Scott Right	Date/Time/305 S = Soil 3 - 25 - 10 SE = Sediment	t DS = Drum Solids t DL = Drum Liquids T = Tissue
	Rejudyished By Rrint Sign	Date/Time 1	125/10 MARNE	Print Sign	Date/Time 1402 SL = Sludge $3-25-10$ W = Water	= Wipe =
	Relinquished By Print Sign Mearth Hock M. Am.	Date/Time 14'	75 Received By 70 C. S. S. L.	ξ. Υ	7	V = V Vegetation $X = O$ ther
	FINAL SAMPLE Disposal Method (e. DISPOSITION	g., Return to	omer,	used in process)	Disposed By	y Date/Time
	And the second s					AND THE RESERVE THE PARTY OF TH

All samples containing hazardous materials shall be picked up by requestor and returned to parent container or site of origin. DISTRIBUTION: White - Remain with Samples Color - Customer BC-6000-828 (09/95)

20100331

	GENERATOR KNOWLEDGE INFORMATIO	N		
1.			mber <u>THS</u>	F'-05779-001
2.	List generator knowledge or description of process that produced sample. Or list description of sample sou Swipe sample from glovebox in building 234-52, room 136.	rce:		
	MSDS Available? No Yes Hanford MSDS No.			
3.	List all waste codes and constituents associated with the waste or media that was sampled, regardless of C	ERCLA status),	
	a) Does the sample contain any of the following listed waste codes? By checking "unknown" the customer understands that no knowledge is available following a ca List Federal Waste Code(s): List Constituent(s):	reful search.		
	P Codes:	O Yes	No	Unknown
	U Codes:	O Yes	No	O Unknown
	K Codes:	O Yes	No	O Unknown
	F Codes:	O Yes	No	O Unknown
b)	List applicable characteristic waste codes, flash point, pH, constituents, and concentrations as appropriate.			
	D001: ☐ FP <100°F ☐ FP ≥100 <140°F ☐ DOT Oxidizer	O Yes	No	Unknown
	D002: pH <2 pH >12.5 Solid Corrosive (WSC2)	O Yes	No	Unknown
	D003: Cyanide Sullide Water Reactive Other (i.e., peroxide former,	O Yes	● No	Unknown
	D004-D043 (Identify applicable waste codes and concentrations): explosive, air reactive)	O Yes	No	Unknown
dì	List any known Land Disposal Restrictions (LDR) subcategories, if applicable (40 CFR 268.40): Not: applicable.			
e)	List any applicable Washington State dangerous waste codes: (not required if			•
		nixture rule for \(\) Yes	ignitability) • No	Unknown
	WT01: Yes ♠ No Unknown WP01: WT02: Yes ♠ No Unknown WP02:	O Yes	No	Unknown
	W001: Yes No Unknown WP03:	Yes	No	Unknown
	List constituents and concentrations: F003:*	O Yes	No	Unknown
·i	Is this mederial TSCA regulated for PCBs? Yes No Unknown Analysis I	Requested		
;	List concentration if applicable: If yes, what is the source of the PCBs? (see TSCA PCB Hanford Site User Guide, DOE/RL-2001-50)			
	PCB Liquid Waste	nnm [Unknown	
	☐ PCB Remediation Waste ☐ PCB R&D Waste ☐ PCB contaminated elect ☐ PCB Spill Material ☐ PCB Item ☐ Other PCB Waste (list)	trical equipmen	nt (capacitor	
5	. Is this material TRU? (a) Yes ONO Unknown			
6	ACCURACY OF INFORMATION			. in Common the co
	Based on my inquiry of those individuals immediately responsible for obtaining this information, that to the entered in this document is true, accurate, and complete	best of my kn	owledge, the	information
	Print & ign 1006 Cathel 1006 Cathe	Date		

RADIOACTI	VF SHIPI	MENT REC	ORD	3. Page 1	00331 of 1 4. Ship	Prenaid	5. V	ia si	te Carrie	^
1. SHIP FROM U.S.							Le shii	PMENT		-
Company CH2MHILL		VERGI GIO	1	ny ATLII	U.S. DEPT. OF	ENERGY C/0	AUTHO	ORIZATIO	N KJ001	
Address PFP	1110		_						NCY RESPONS	E
		···	_	ss <u>222-S</u>	17 7				-509-373-	
City, State, Zip 200 We				tate, Zip 200			1	ency Res		
Contact Jeff Widne	<u> </u>			on <u>Gerald F</u>	Ritenour	······································	Guide(
Phone 372-3090			Phone	372-2742			_ 163			
HM 8. Proper Shippi		erial, Type A	Nackage						RI HAZ SUB HAZ 7	UN ID UN 2915
9. No. Pkg. Model Pac		COC/Spec	Serial N		I leat	opes	C.S.I.	T.I.	Bq/Package	Gr. Wt. Kg.
1 Viking	DOT	7A TYPE A	S/N 1		Pu239Pu240Am		N/A		1.56E-5 TBq	9 Kg
10. Identify for Norm		11. Highw	ay Route C	ontrolled Qua	intity	12.	·····	ABELS	APPLIED	
Physical Form Sol.	id	1 7		ipment with in	structions	Radioa	ctive :	Yello	w - II	
		☐ Placar	ds Applied		075-03	13.	ADDITIO	NAL LA	BELS / MARKI	NGS
Chemical Form Oxí	de	☐ IN ID	Excepted,	Grams 1.3						
HM 8. Proper Shippi			Marking _					aa	HAZ SUB HAZ	UN ID-
S. Frober on pp.	ing Italiic.							1 131	- 30BTIAL	
9. No. Pkg. Model Rac	kage	COC/Spec	Serial No	o. Seal No.	Isot	opes	C.S.I.	T.I.	Bg/Package	Gr. Wt. Kg.
			<u> </u>							
10. Identify for Norm	nal Form Only	=	•	ontrolled Qua	•	12.		ABELS	APPLIED	
Physical Form			sive Use Sh ds Applied	ipment with ir	structions					
Chemical Form			_	Grams		13.	ADDITIO	NAL LA	BELS / MARKII	NGS
Chemical Form			Marking _							
HM 8. Proper Shippi	ng Name:							PR	HAZ SUB HAZ	UN ID
9. No. Pkg. Model Pac	kage	COC/Spec	Serial No	o. Seal No.	Isot	opes	C.S.I.	T.J.	Bg/Package	Gr. Wt. Kg.
10. Identify for Norm	nal Form Only		-	ontrolled Qua	•	12.		ABELS	APPLIED	
Physical Form		1 ==	ive Use Sh ds Applied	ipment with in	structions					
Chamical Form		1 ====		Grams		13.	ADDITIO	NAL LA	BELSLMARKI	NGS
Chemical Form			Marking							
		14. Shipment D				Tall	C.S.I.	T.I.	Bq/Package	Gr. Wt. Kg.
		1.525				Shipment Tota			1.56E-5 TBq	9
15. Surface Dose Rat	•	Dose Rate @ 1 Met			Smears of Outer		Į.	LOADC	REXCLUSIVE	
<0.005 or <0.2 mrs		<0.005 or <0.5 or		-	<4.0 Bq (220 d <0.4 Bq (22 dp		Surface @ 2 mete		2 mSv/hr (200 m <0.1 mSv/hr (10 r	•
Additional Data and Instr	`			,,,,,	₹Tbl. 2-2 HNF-		@ Cab		<0.02 mSv/hr (2 r	•
(inc. Readings on Interna							or slee	per	(Using N+ß γ)	
					345	Z Z Z Z	7325G	05	Date 03-29	5-10
16.		ISPORTER			17.		RECEIVE	R		
Vehicle Number	_ // //	SIGNATURE 1	L PRIN	TNAME	RECEIVER SIG	NATURE	PRINT N	IAME	Date 7	
682 02767			napla	2 Huck	James	305	8 211	~ ~	" J\X	5 /,
18. This is to certify t	that the above				described nackag	ed marked and	laheled a	nd are in	n proper condition	n for
transportation ac Certifier's Signature	cording to the	applicable regula	itions of the	e Department	of Transportation.				i proper conditio	11 101
Certiner's Signature	PIN	n name		On bena	If of DOE-RL Date		Organizat	ion		
(VATI)	$()$ \leq	++1111			3	125/10		SC		
19.	NO 02	on yyeu	∠5 AUT	HORIZATION	N FOR SHIPMEN	r ,				
AIR TRANSPORT		AIRCRAFT		PASSENGER			nsions (cm)			
CERTIFICATION N/A		Aircraft Only els Applied	∐ Ltd Qty	,	rch/Medical Diagn	l l				
20.		1-1	<3 T.I.		Medical Research	ch	·			
Survey No.		Date Sh		Routing	THORIZATION				ETA	
Approved for Shipment C	Offsite			L					Date	
									Date	
									A-6003-214.	1 (REV 2)